



**Technical Service
BULLETIN**

January 23, 2006

Title:

**TOWING RECEIVER HITCH INSTALLATION
INSTRUCTIONS REVISION**

Models:

'06 RAV4

AX001-06
ACCESSORIES

Introduction The 2006 model year RAV4 Towing Receiver Hitch kit produced prior to 12/1/2005 (date code 01L05) includes installation instructions with incorrect torque specifications for the driver's side bolts, section 9, steps (a) and (b).

Correct torque specifications can be found in the Installation Instructions section of this bulletin, or in the Technical Information System (TIS), 2006 model year RAV4: *Accessories: Installation Instructions: 2006 RAV4 Towing Hitch PT228-42061.*

- Applicable Vehicles**
- **2006** model year **RAV4** vehicles.

Parts Information

PREVIOUS PART NUMBER	CURRENT PART NUMBER	PART NAME	QTY
PT228-42061	Same	Towing Receiver Hitch	1

Installation Instructions

The corrected installation instructions for section 9, steps (a) and (b) are as follows:

9. Tighten Driver's Side Bolts

- (a) Tighten the three (3) M8 bolts on the bumper brackets to 38 N-m (28 lbf-ft).
- (b) Tighten all M12 x 35 bolts to 80 N-m (60 lbf-ft) in the sequence shown. (Fig. 9-1) 1-9.

Warranty Information

OP CODE	DESCRIPTION	TIME	OFP	T1	T2
N/A	Not Applicable to Warranty	-	-	-	-

