

CUSTOMER #: 240237

744058



DANNY TER HAAR

INVOICE

DCH TOYOTA OF OXNARD

1631 AUTO CENTER DRIVE · OXNARD, CA 93036
TEL (805) 988-2300 · FAX (805) 988-2386
www.toyotaofoxnard.com

PAGE 1

HOME: CONT:312-1176 BAR # ARD159928 EPA # CAD983642141
BUS: CELL:805-312-1176 SERVICE ADVISOR: 1003 RAYMOND MARTIN

COLOR	YEAR	MAKE/MODEL	VIN	LICENSE	MILEAGE IN / OUT	TAG	
WHITE	14	TOYOTA RAV4	2T3YL4DV2EW002696	7FOT096	15945/15955	T4422	
DEL. DATE	PROD. DATE	WARR. EXP.	PROMISED	PO NO.	RATE	PAYMENT	INV. DATE
25MAY14 DD			18:00 06MAY15			CASH	05MAY15
R.O. OPENED	READY	OPTIONS: ENG:Electric					
09:10 30APR15	10:13 05MAY15						

LINE OPCODE TECH TYPE HOURS LIST NET TOTAL

A CHECK WHY DRIVER SIDE FRONT WINDOW FAILS TO CLOSE WHEN OPERATING WITH VEHICLE IN MOTION. CROSS WINDS SEEMS TO MAKE THE CONCERN HAPPEN.

CAUSE: OTHER

672011 F. DR WNDW REGULATOR SUBASSY ONE SIDE
1185 Varughese, Philip LIC#: Y
WT93

(N/C)

FC: 91,99 PART#: COUNT:
CLAIM TYPE: RG
AUTH CODE:

PARTS: 0.00 LABOR: 0.00 OTHER: 0.00 TOTAL LINE A: 0.00
REMOVED DOOR PANEL TO INSPECT INTERNAL COMPONENTS

B DRIVE LINE ASSEMBLY (PER FTS)

CAUSE: IMPROPER FREEPLAY

890501 ELECTRIC VEHICLE TRACTION MOTOR ASSEMBLY
1185 Varughese, Philip LIC#: Y
WT93

(N/C)

3 12486 DEXRON VI

(N/C)

2 90080-17238 NUT, LOCK

(N/C)

Z REPAIRED STRIPPED THREADS ON SUB-FRAME
1185 Varughese, Philip LIC#: Y
WT93

(N/C)

FC: 91,40 PART#: COUNT:
CLAIM TYPE: RG
AUTH CODE:

SJBL RENTAL

WT93

(N/C)

PARTS: 0.00 LABOR: 0.00 OTHER: 0.00 TOTAL LINE B: 0.00
REPLACED TRACTION MOTOR ASSEMBLY

Original Estimate (Parts & Labor)	Total Additional Cost Authorized	Approved By:	Date & Time	Authorization Obtained By:
\$	\$			<input type="checkbox"/> Telephone <input type="checkbox"/> Fax (See Attached) <input type="checkbox"/> E-mail (See Attached)
Revised Estimate	\$			<input type="checkbox"/> Telephone <input type="checkbox"/> Fax (See Attached) <input type="checkbox"/> E-mail (See Attached)

By signing below, you acknowledge that you were notified of and authorized the Dealership to perform the services/repairs itemized in this invoice and that you received (or had the opportunity to inspect) any replaced parts as requested by you.

NOTICE TO CONSUMER: PLEASE READ IMPORTANT INFORMATION ON BACK.

*HAZARDOUS WASTE DISPOSAL COSTS: We have added this charge to cover costs associated with the handling, management and disposal of toxic wastes or hazardous substances under California and Federal Law.

ALL PARTS ARE NEW UNLESS OTHERWISE INDICATED.
 Some Parts Not Returnable

DESCRIPTION	TOTALS
LABOR AMOUNT	
PARTS AMOUNT	
GAS, OIL, LUBE	
SUBLET AMOUNT	
WASTE DISPOSAL COSTS *	
TOTAL CHARGES	
COVERAGE	
SALES TAX	

DATE CUSTOMER SIGNATURE AUTHORIZED DEALERSHIP REPRESENTATIVE SIGNATURE PLEASE PAY THIS AMOUNT